



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8 999 18TH STREET- SUITE 300

DENVER, CO 80202-2466
Phone 800-227-8917
http://www.epa.gov/region08

Ref: 8EPR-SR

June 6, 2006

CHARLES & RENEE COUSINS 3535 E 26TH AVE DENVER CO 80205

RE: 1725-1745 BRUCE RANDOLPH AVE

Dear Owner,

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: 1725-1745 BRUCE RANDOLPH AVE	EPA Cleanup Levels
Lead	
220 parts per million (ppm)	above 400 ppm
Arsenic	
5 ppm	above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely.

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-1725-BR-01

Client Project ID: 213001.01

Date Collected:
Date Received:

5/16/06 5/18/06 Lab Work Order: 06-3174

Lab Sample ID:

06-3174-52

Sample Matrix:

Soil

TOTAL.	METAL	S
IVIAL		

Method: SW6020 Prep Method: SW3050

Date Prepared: 5/30/06 Lab File ID: 06
Date Analyzed: 5/31/06 Method Blank: M

060531A.B\098SMPL.D Dilution Factor: 1

Date Analyzed: 5/31/06 Method Blank: MB-10028 Lab Fraction ID: 06-3174-52A

 Analytes
 CAS Number
 Result
 LQL
 Units

 Arsenic
 7440-38-2
 4.3
 0.38 mg/Kg

 Lead
 7439-92-1
 180
 0.26 mg/Kg

Analyst

Approved

lt

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

I - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

 -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL. Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-1725-BR-02 Client Project ID: 213001.01

Date Collected:

Date Received:

5/16/06

5/18/06

Lab Work Order: 06-3174

06-3174-53 Lab Sample ID:

Sample Matrix: Soil

TOTAL METALS

Method: SW6020 Prep Method: SW3050

Date Prepared: 5/30/06 060531A.B\099SMPL.D **Dilution Factor:** Lab File ID:

Date Analyzed: 5/31/06 Method Blank: MB-10028 Lab Fraction ID: 06-3174-53A

Analytes **CAS Number** Result LQL Units 7440-38-2 4.6 0.39 Arsenic mg/Kg 7439-92-1 330 0.26 Lead mg/Kg

Analyst

Approved

Qualiflers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits U - Compound analyzed for but not detected

X - See case narrative

* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/1/06

Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-1725-BR-03 Client Project ID: 213001.01 Date Collected: 5/16/06 Date Received: 5/18/06

Lab Work Order: 06-3174 06-3174-54 Lab Sample ID: Sample Matrix: Soil

Method: SW6020	TOTAL METALS Prep Method: SW3050					
Date Prepared: 5/30/06 Date Analyzed: 5/31/06 Analytes	Lab File ID: 060531A.B\100SMPL.D Method Blank: MB-10028		Dilution Factor: Lab Fraction ID: 06-3174-54A			
	CAS Number	Result	LQL	Units		
Arsenic	7440-38-2	4.4	0.40	mg/Kg		
Lead	7439-92-1	150	0.27	mg/Kg		

Analyst

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

I - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits U - Compound analyzed for but not detected

X - See case narrative
*-Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.


Approved

Definitions: NA - Not Applicable LQL - Lower Quantitation Limit

Surr - Surrogate









UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8 Victor Ketellapper Phone 800-227-8917 http://www.epa.gov/region08

CONSENT FOR ACCESS TO PROPERTY

Name: Charles & Renee Cousins (or current property owner)

Location of Property: 1725-1745 Bruce Randolph Ave

Property ID: 6168

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having continued access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act. (CERCLA or Superfund), 42 U.S.C. § 9601 et seq.

Charles R. Cousins
Printed Name
303-321-4428

Tharles R. Coursens

Phone Number

Date